



BOLT TOGETHER ALUMINUM FRAMES. FRAMES ARE BOLTED RATHER THAN WELDED, THIS REDUCES STRESS CRACKING IN THE ALUMINUM PARTS DUE TO METAL FATIGUE

TERRA BOUND SOLUTIONS

Office: 1-877-857-2915
Fax: 281-288-2870

www.TerraBoundSolutions.com
20020 Hickory Twig Way * Spring, TX * 77388

GENERAL NOTES:		UNLESS OTHERWISE SPECIFIED:	NAME	DATE	TITLE:
		DIMENSIONS ARE IN INCHES TOLERANCES: FRACTIONAL ± 1/32 DECIMAL ± 1/2" DO NOT SCALE DRAWING	DRAWN: DAT	3/11/2015	
		MATERIAL:	ENG APPR:		DESC: 2 ROW ALUMINUM BLEACHER W/ MUDSILLS
			MFG APPR:		S:\CADD\DWGS\Solidworks\Bleachers\BLA\BLA Assemblies\Bleachers (17in)
			UNIT/ISSUED COMMENTS:	3/11/2015 9:03:32 AM	SIZE PART NO. BLA2A15 (SPEC) REV
		SHEET 1 OF 1			
Path to Part or Assy - BLA2A15 (SPEC)		S:\CADD\DWGS\Solidworks\Bleachers\BLA\BLA Assemblies\Bleachers (17in)		Default	